

#3  
J. Drawing





FIG. 1a


10020134 "12101  
T0822T"4E200F

130



CO SIDE DSL  
Modem  
(DSLAM)  
132

Twisted  
Copper Pair  
140



CPE DSL  
Modem  
142

FIG. 1b

FIG. 1c

150




FIG. 1c

FIG. 1d




FIG. 1d




FIG. 2




FIG. 3




FIG. 4




FIG. 5






Figure 6




Figure 7




FIG. 8




FIG. 9




FIG. 10a




FIG. 10b




Fig. 10c




Fig. 11




Fig. 12




Fig. 13



1400




FIG. 14a

1450




FIG. 14b






FIG. 16

1700




FIG. 17

10020134-121801




FIG. 18a

10020144-1001




FIG. 18b

1000134-120001




FIG. 18c